

# PCD/CVD

# Insert



## SCMW

### Stocked Sizes:\*

- 1 = 1 Edge
- 2 = 2 Edges
- 3 = 3 Edges
- 4 = 4 Edges
- 6 = 6 Edges

### Blank Sizes:

- X = 0.050 Depth of Cut
- Z = 0.100 Depth of Cut



BLANK SIZE	Type		PCD (Grades)							CVD (Grade)			Dimensions (Inches)			
	ANSI	ISO	UF	F	M	C	MM	MC					D	T	R	H
X	SCMW2.51.50	SCMW070201											0.313	0.094	0.004	0.134
X	SCMW2.51.50.5	SCMW070202											0.313	0.094	0.008	0.134
X	SCMW2.51.51	SCMW070204											0.313	0.094	0.016	0.134
X	SCMW21.50	SCMW060202											0.250	0.125	0.005	0.134
X	SCMW21.51	SCMW060204											0.250	0.125	0.016	0.134
X	SCMW21.52	SCMW060208											0.250	0.125	0.031	0.134
X	SCMW32.50	SCMW09T301											0.375	0.156	0.004	0.173
X	SCMW32.50.5	SCMW09T302											0.375	0.156	0.008	0.173
X	SCMW32.51	SCMW09T304											0.375	0.156	0.016	0.173
X	SCMW32.52	SCMW09T308											0.375	0.156	0.031	0.173

\* If Blank = Non-Stocked. Will produce to order.