

# PCD/CVD

# Insert



## TPMW

### Stocked Sizes:\*

- 1 = 1 Edge
- 2 = 2 Edges
- 3 = 3 Edges
- 4 = 4 Edges
- 6 = 6 Edges

### Blank Sizes:

- X = 0.050 Depth of Cut
- Z = 0.100 Depth of Cut



BLANK SIZE	Type		PCD (Grades)							CVD (Grade)			Dimensions (Inches)				
	ANSI	ISO	UF	F	M	C	MM	MC			CVD			D	T	R	H
X	TPMW21.50	TPMW110202			1									0.250	0.094	0.008	0.110
X	TPMW21.51	TPMW110104			1									0.250	0.094	0.016	0.110
X	TPMW220.5	TPMW110302												0.250	0.125	0.008	0.134
X	TPMW221	TPMW110304												0.250	0.125	0.016	0.134
X	TPMW222	TPMW110308												0.250	0.125	0.031	0.134
X	TPMW32.50	TPMW16T302												0.375	0.094	0.008	0.134
X	TPMW32.51	TPMW16T304			1									0.375	0.094	0.016	0.134
X	TPMW32.52	TPMW16T308			1									0.375	0.094	0.031	0.134

\* If Blank = Non-Stocked. Will produce to order.